

Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: EXTRACTION OIL & GAS INC

Location ID: 320561

Inspection Document #: 696105598

Adams County, CO

SESE Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Maul 44-26
Location ID:320561



Photo 1. Taken from the beginning of the access road, facing west. Photo illustrates the reclaimed location has a large infestation of undesirable vegetation (e.g. russian thistle and kochia). No evidence of oil and gas equipment observed.

Inspection Photos
Location Name: Maul 44-26
Location ID:320561



Photo 2. Taken from the well location, facing east. Photo illustrates presence of undesirable vegetation, outlined in red.

Inspection Photos
Location Name: Maul 44-26
Location ID:320561



Photo 3. Taken from the western portion of the location, facing west. Reference area pictured.