

Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320606

Inspection Document #: 696105600

Adams County, CO

NESE Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Maul 43-26
Location ID: 320606



Photo 1. Taken from the entrance to the access road, facing southwest. Photo illustrates the location appears to have been reclaimed with no visible evidence of oil and gas equipment. Undesirable vegetation observed in foreground (e.g. kochia and russian thistle) and throughout portions of the reclaimed areas.

Inspection Photos
Location Name: Maul 43-26
Location ID: 320606



Photo 2. Taken from the western portion of the well location, facing east. See comments in Photo 1.