

Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320555

Inspection Document #: 696105602

Adams County, CO

NWSE Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Maul 33-26
Location ID: 320555



Photo 1. Taken near the well location/access road transition, facing north. Photo illustrates presence of undesirable vegetation (e.g. kochia and russian thistle) outlined in red.

Inspection Photos
Location Name: Maul 33-26
Location ID: 320555



Photo 2. Facing south, see comments in Photo 1.

Inspection Photos
Location Name: Maul 33-26
Location ID: 320555



Photo 3. Taken from the western portion of the well location, facing east. See comments in Photo 1.