

# Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320550

Inspection Document #: 696105604

Adams County, CO

SESW Section 26 T1S R66W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Leech 24-26  
Location ID: 320550



**Photo 1.** Taken from the access road, facing southeast. Photo illustrates evidence of undesirable vegetation (e.g. kochia and russian thistle) near the well location. The access road is currently serving a nearby well (API#001-09652) and will need to be reclaimed upon P&A of that well.



Inspection Photos  
Location Name: Leech 24-26  
Location ID: 320550



**Photo 2.** Facing east at the well location. Photo illustrates areas non-uniform vegetation cover resulting in bare soil near the former well location; a vegetation assessment will be conducted at a later date to ensure compliance with Rule 1004 standards.



Inspection Photos  
Location Name: Leech 24-26  
Location ID: 320550



**Photo 3.** Facing north, see comments in Photos 1 & 2.