

Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320603

Inspection Document #: 696105606

Adams County, CO

SWSW Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Leech 14-26
Location ID: 320603



Photo 1. Taken east of the well, facing west. Photo illustrates undesirable vegetation (e.g. kochia and russian thistle) observed around the location and near the well head.

Inspection Photos
Location Name: Leech 14-26
Location ID: 320603



Photo 2. Facing east, See comments in Photo 1.