

Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 319807

Inspection Document #: 696105610

Adams County, CO

NESW Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Leech 1
Location ID: 319807



Photo 1. Taken from the southern portion of the well location, facing northwest. It appears the operator has performed final reclamation work with no visual evidence of oil and gas equipment. This well is on a shared tank battery location (319807) that is currently “shut in” with plans for abandonment. This location will be re-inspected at a later date to verify vegetation, and final reclamation activities for the tank battery location.

Inspection Photos
Location Name: Leech 1
Location ID: 319807




Photo 2. Facing east. See comments in Photo 1.