

Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 319807

Inspection Document #: 696105612

Adams County, CO

NESW Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Leech-61S66W 26NESW
Location ID: 319807



Photo 1. Taken from the northern portion of the location, facing north. Photo illustrates the access roads and undesirable vegetation observed during inspection (e.g. kochia and russian thistle) outlined in red.



Photo 2. Taken from the north end of location, facing southeast. Photo illustrates undesirable vegetation (e.g. russian thistle and kochia) outlined in red, and CO List C Noxious Weed (e.g. common mullein) outlined in green.



Photo 1. Close up photo of CO List C Noxious Weed (Common Mullein).

Inspection Photos
Location Name: Leech-61S66W 26NESW
Location ID: 319807



Photo 4. Taken from tank battery, facing north. Photo illustrates road maintainer/grader currently stored on location. This is considered unused equipment and needs to properly removed.

Inspection Photos
Location Name: Leech-61S66W 26NESW
Location ID: 319807



Photo 5. Taken from the north end of location, facing south. Photo illustrates undesirable vegetation (e.g. russian thistle and kochia) outlined in red.

Inspection Photos
Location Name: Leech-61S66W 26NESW
Location ID: 319807



Photo 6. Taken from the southern portion of the location, facing northwest. See comments in Photo 5.