

Inspection Photos

Location Name: 70 RANCH USX BB/25-07P

Location #: 415365



Photo #1

70 Ranch USX BB 25-07P (123-31070) Wellsite
Temporarily Abandoned | TA



Photo #2

70 Ranch USX BB 25-07P Battery site
Abandoned: ALL Equipment Removed