

Inspection Photos

Location Name: COCKROFT USX A-66N64W/11SENE

Location #: 333034



Photo #1

Cockroft USX A 11-8 (123-24711) Wellsite
Temporarily Abandoned | TA



Photo #2

Cockroft USX A 11-8 Battery site
Abandoned: ALL Equipment Removed