

Inspection Photos
Location Name: COCKROFT-66N64W/11NWSE
Location #: 305195



Photo #1

Cockroft 33-11 (123-22627) Wellsite

Shut-In | SI

CA: Weeds need cleared

Common (shared) flowline w/ Cockroft 43-11



Photo #2

Cockroft 44-11, 33-11, 34-11, 43-11 Battery site

Inactive | Shut-down

Equipment documented: Loc. # 332161



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources