

Inspection Photos
Location Name: COCKROFT-66N64W/11NWSE
Location #: 305195



Photo #1

Cockroft 33-11 (123-22627) Wellsite

Shut-In | SI

CA: Weeds need cleared

*Common (shared) flowline w/ Cockcroft 43-11
prior photo*



Photo #2

Cockroft 33-11 Wellsite

Shut-In | SI

CA: Resolved. Weeds NOW mitigated.

Operator provided photo: 2022-11-23



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COCKROFT-66N64W/11NWSE

Location #: 305195



Photo #3

Cockroft 44-11, 33-11, 34-11, 43-11 Battery site

Inactive | Shut-down

Equipment documented: Loc. # 332161

prior photo