

# Inspection Photos

API: 071-06426

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/28/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06426 | Date: 11/28/2022

## Inspection Photos



**Photo 1.** Facing north along the access road. There is erosion along the roadside that needs to be repaired with BMP's



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06426 | Date: 11/28/2022

## Inspection Photos



**Photo 2.** Facing north along the access road. There is erosion along the roadside that needs to be repaired with BMP's



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06426 | Date: 11/28/2022

## Inspection Photos



**Photo 3.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06426 | Date: 11/28/2022