

Inspection Photos

API: 071-08523

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/28/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08523 | Date: 11/28/2022

Inspection Photos



Photo 1. Facing southeast along the access road. There is an open hole at the culvert crossing that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08523 | Date: 11/28/2022

Inspection Photos



Photo 2. There is a hole in the culvert at the drainage crossing causing material to cave in in this area of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08523 | Date: 11/28/2022

Inspection Photos



Photo 3. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08523 | Date: 11/28/2022