

## Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16SENW

Location #: 310240



**Photo #1**

**Bashor State AA 16-6 (123-26118) Wellsite**

**Temporarily Abandoned | TA**

*CA: Weeds need cleared*

*prior photo*



**Photo #2**

**Bashor State AA 16-6 Wellsite**

**Temporarily Abandoned | TA**

**CA: Resolved. Weeds NOW mitigated.**

*Operator provided photo: FIRR*

## Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16SE NW

Location #: 310240



### Photo #3

**Bashor State AA 16-5, 16-3, 16-04, 16-6, 16-12,  
16-19, 16-20** Battery site

**Abandoned: ALL Equipment Removed**  
*prior photo*