

Inspection Photos

November 23, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 415655

Location Name: SAVAGE 17-05 PAD

Inspection Document #: 702800956

Garfield County, CO

SWNW Section 17 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE 17-05 PAD
Location ID: 415655



Photo 1. Photo taken from the southern interim area shows an overview of the location. Photo also shows a dense patch of plumeless thistle.



Inspection Photos
Location Name: SAVAGE 17-05 PAD
Location ID: 415655



Photo 2. Photo shows the western interim area. Perennial grasses and forbs appear widespread, however snow cover obscured vegetation. A follow up inspection is required during the growing season.



Photo 3. Photo shows portions of the interim areas which appear dominated by annual, undesirable plant species/weeds.



Inspection Photos
Location Name: SAVAGE 17-05 PAD
Location ID: 415655



Photo 4. Photo taken from the east of the location shows what appears to be a topsoil stockpile at the base of the fill slope.



Photo 5. Photo taken from the north of the location shows what appears to be a topsoil stockpile at the base of the northwestern fill slope.



Inspection Photos
Location Name: SAVAGE 17-05 PAD
Location ID: 415655



Photo 6. Photo shows production areas.



Photo 7. Photo shows production areas.



Inspection Photos
Location Name: SAVAGE 17-05 PAD
Location ID: 415655



Photo 8. Photo shows production areas.

