

Inspection Photos

November 23, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 413221

Location Name: 17L/794

Inspection Document #: 702800958

Garfield County, CO

NWSW Section 17 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: 17L/794
Location ID: 413221

11/23/22
+39.435263,-107.915688
8° N



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: 17L/794
Location ID: 413221



Photo 2. Photo taken from the well area shows one of two leaking corrosion inhibitor tanks. Fluid observed outside secondary containment on the ground.



Photo 3. Photo taken from the well area shows one of two leaking corrosion inhibitor tanks.

Inspection Photos
Location Name: 17L/794
Location ID: 413221



Photo 4. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800958

Inspection Photos
Location Name: 17L/794
Location ID: 413221



Photo 5. Photo shows production areas.



Photo 6. Photos show production areas.



Inspection Photos
Location Name: 17L/794
Location ID: 413221



Photo 7. Photo taken from the south shows interim areas. Perennial grasses evident throughout. Follow up inspection required during growing season. Noxious weeds observed occasionally throughout.



Photo 8. Photo taken from the southern interim area shows an example of plumeless thistle (List B Noxious). Noxious weeds observed occasionally throughout interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800958

Inspection Photos
Location Name: 17L/794
Location ID: 413221



Photo 9. Photo shows compaction and gravel degradation of pad surface.



Photo 10. Photo shows compaction and gravel degradation of pad surface

