

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NENE

Location #: 302510



Photo #1

Bashor State AA 16-01 (123-29255) Wellsite

Temporarily Abandoned | TA

CAs: Need well sign w/ Emergency number

Weeds need cleared

prior photo



Photo #2

Bashor State AA 16-01 Wellsite

Temporarily Abandoned | TA

CAs: Resolved. Sign w/ Emergency number posted.

Weeds NOW mitigated.

Operator provided photo: FIRR

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16NENE

Location #: 302510



Colorado Oil & Gas Conservation Commission
Weld County
+40.485738, -104.432768
327° NW
2022-10-27 15:40

Photo #3

**Bashor State AA 16-08, 16-01, 16-02, 16-07, 16-17,
16-18**

Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Bashor State 16-09, 16-22;

Plugged & Abandoned | PA

prior photo



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources