

Inspection Photos

API: 071-06631

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/28/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 11/28/2022

Inspection Photos



Photo 1. Facing north toward the beginning of the access road. The road side was hydromulched and seeded..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 11/28/2022

Inspection Photos



Photo 2. Facing northwest along the access road to the well site. This area of erosion was repaired and stabilized. Snow cover obscures this area at time of inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 11/28/2022

Inspection Photos



Photo 3. Facing east along the access road to the well site. This area of erosion was repaired and stabilized. Snow cover obscures this area at time of inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 11/28/2022

Inspection Photos



Photo 4. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 11/28/2022