

Inspection Photos

November 23, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 335006

Location Name: SAVAGE-67S94W/8NWNW

Inspection Document #: 702800963

Garfield County, CO

NWNW Section 8 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-67S94W/8NWNW
Location ID: 335006



Photo 1. Photo taken from the north shows an overview of the location.

Inspection Photos
Location Name: SAVAGE-67S94W/8NWNW
Location ID: 335006



Photo 2. Photo shows production areas.



Photo 3. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800963

Inspection Photos
Location Name: SAVAGE-67S94W/8NWNW
Location ID: 335006



Photo 4. Photo shows production areas.



Inspection Photos
Location Name: SAVAGE-67S94W/8NWNW
Location ID: 335006



Photo 5. Photos show two secondary containment tanks lacking wildlife protection BMPs.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702800963

Inspection Photos
Location Name: SAVAGE-67S94W/8NWNW
Location ID: 335006



Photo 6. Photo shows interim areas are dominated by introduced perennial grasses smooth brome and crested wheatgrass.




Photo 7. Photo shows an example of plumeless thistle (List B Noxious) found occasionally throughout the interim areas.

