

Inspection Photos

November 23, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 334748

Location Name: WELLS-66S94W/32NESW

Inspection Document #: 702800969

Garfield County, CO

NESW Section 32 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WELLS-66S94W/32NESW
Location ID: 334748



Photo 1. Photo shows a leaking corrosion inhibitor tank.



Inspection Photos
Location Name: WELLS-66S94W/32NESW
Location ID: 334748



Photo 2. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800969

Inspection Photos
Location Name: WELLS-66S94W/32NESW
Location ID: 334748



Photo 3. Photo shows production areas.



Photo 4. Photo shows production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800969

Inspection Photos
Location Name: WELLS-66S94W/32NESW
Location ID: 334748



Photo 5. Photo shows interim areas to the north.



Photo 6. Photo shows interim areas to the south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800969