

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16SENE

Location #: 302512



Photo #1

Bashor State AA 16-08 (123-29257) Wellsite

Temporarily Abandoned | TA

CA: Weeds need cleared

prior photo




Photo #2

Bashor State AA 16-08 Wellsite

Temporarily Abandoned | TA

CA: Resolved. Weeds NOW mitigated.

Inspection Photos

Location Name: BASHOR STATE AA-66N63W/16SENE

Location #: 302512



Colorado Oil & Gas Conservation Commission
Weld County
+40.485736 -104.432768
327° NW
2022-10-27 15:40

Photo #3

**Bashor State AA 16-08, 16-01, 16-02, 16-07, 16-17,
16-18** Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Bashor State 16-09, 16-22;

Plugged & Abandoned | PA

prior photo