

Final Reclamation Inspection

October 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 331314

Inspection Document #: 701900750

NESW Section 29 T6N R63W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: J & L Farms 29B
Location ID: 331314



Photo 1. 2020 aerial imagery of the well pad. Note: tank battery highlighted in blue is associated with the J & L Farms 14-19 well API #123-14318.

Inspection Photos
Location Name: J & L Farms 29B
Location ID: 331314



Photo 2. Overview photo of the well pad taken at ground level from the eastern edge facing west. Note: well pad falls within a storage area for Wells Ranch.