

Final Reclamation Inspection

October 20th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 319583

Inspection Document #: 701900760

SESW Section 28 T5N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mellon 28-2
Location ID: 319583



Photo 1. 2020 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: Mellon 28-2
Location ID: 319583



Photo 2. Overview photos of both the well pad (left) and tank battery (right). Note: site is scheduled for maintenance in 2022 and will receive a no status overall per the ADC agreement.