

Final Reclamation Inspection

October 21st, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323254

Inspection Document #: 701900766

NWNE Section 24 T2N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Moore 31-24C
Location ID: 323254



Photo 1. 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Moore 31-24C
Location ID: 323254



Photo 2. Overview photo of the well pad taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Moore 31-24C
Location ID: 323254



Photo 3. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Moore 31-24C
Location ID: 323254



Photo 4. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad is dominated by Canada thistle, a Colorado List B noxious weed.

Inspection Photos
Location Name: Moore 31-24C
Location ID: 323254



Photo 5. Well pad reference area. Note: no Canada thistle observed in reference area.

Inspection Photos
Location Name: Moore 31-24C
Location ID: 323254



Photo 6. Overview photo of the tank battery taken at ground level from the eastern edge facing west.

Inspection Photos
Location Name: Moore 31-24C
Location ID: 323254





Photo 7. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Moore 31-24C
Location ID: 323254



Photo 8. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery falls within a residential area, no signs of oil and gas operations.