

Inspection Photos

November 28, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335544

Location Name: Norcross-66S93W /13NESW

Inspection Document #: 702800982

Garfield County, CO

NESW Section 13 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Norcross-66S93W /13NESW
Location ID: 335544



Photo 1. Photo taken from Location entrance shows an overview of the Location.

Inspection Photos
Location Name: Norcross-66S93W /13NESW
Location ID: 335544



Photo 2. Photos taken from the east of the Location shows erosion occurring on cut slopes.



Inspection Photos
Location Name: Norcross-66S93W /13NESW
Location ID: 335544



Photo 3. Photo shows a tank battery sign.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800982

Inspection Photos
Location Name: Norcross-66S93W /13NESW
Location ID: 335544



Photo 4. Photos show production areas