

Inspection Photos

API: 071-08542

Operator: OGRIS OPERATING LLC

Inspection Date: 11/30/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08542 | Date: 11/30/2022

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08542 | Date: 11/30/2022

Inspection Photos



Photo 2. Facing toward the production equipment. The sign has blown off the shed and needs to be reinstalled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08542 | Date: 11/30/2022

Inspection Photos



Photo 3. There is a dripping water leak at the wellhead that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08542 | Date: 11/30/2022