

# Inspection Photos

API: 071-09325

Operator: OGRIS OPERATING LLC

Inspection Date: 11/30/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09325 | Date: 11/30/2022

## Inspection Photos



**Photo 1.** Facing southwest along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09325 | Date: 11/30/2022

## Inspection Photos



**Photo 2.** Facing toward the wellsite. There are panel laying on the ground that need to be removed or re-installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09325 | Date: 11/30/2022