

Inspection Photos  
Location Name: NEWLANDER 1  
Location ID: 320214



Photo# 1 Crude tank.



Photo# 2 P/W tank.

Inspection Photos  
Location Name: NEWLANDER 1  
Location ID: 320214



Photo# 3 Separator & meter house.



Photo# 4 Pump Jack.