

Inspection Photos

November 28, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 335384

Location Name: LAZIER-66S93W/23SESE

Inspection Document #: 702800978

Garfield County, CO

SESE Section 23 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LAZIER-66S93W/23SESE
Location ID: 335384



Photo 1. Photo taken from the location entrance to the west shows an overview of the location.



Inspection Photos
Location Name: LAZIER-66S93W/23SESE
Location ID: 335384



Photo 2. Photo shows decommissioned production facilities. Note pipe equipment requiring removal.

Inspection Photos

Location Name: LAZIER-66S93W/23SESE

Location ID: 335384



Photo 3. Photo shows an old equipment footprint.



Photo 4. Photo shows areas at the northwest of the location colonized entirely by cheatgrass (annual, List C Noxious).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800978

Inspection Photos
Location Name: LAZIER-66S93W/23SESE
Location ID: 335384



Photo 5. Photo shows an example of compacted graveled areas of the pad surface requiring reclamation.



Inspection Photos
Location Name: LAZIER-66S93W/23SESE
Location ID: 335384



Photo 6. Photo shows interim areas to the southeast vegetated with perennial grasses and shrubs.

