

# Inspection Photos

November 28, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 324257

Location Name: BENZEL DISPOSAL-66S93W/26NWSE

Inspection Document #: 702800987

Garfield County, CO

NWSE Section 26 T6S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: BENZEL DISPOSAL-66S93W/26NWSE

Location ID: 324257



**Photo 1.** Photo taken from the south shows an overview of the reclaimed location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800987

## Inspection Photos

Location Name: BENZEL DISPOSAL-66S93W/26NWSE

Location ID: 324257



**Photo 2.** Photo shows an example of the contrast between areas which appear to have lower cover of perennial grasses (right) and good establishment of perennial grasses (left).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800987