

# Inspection Photos

November 28, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334649

Location Name: GMR-67S93W/3SWSW

Inspection Document #: 702800991

Garfield County, CO

SWSW Section 3 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GMR-67S93W/3SWSW  
Location ID: 334649



**Photo 1.** Photo taken from the northeast shows an overview of the location.

Inspection Photos  
Location Name: GMR-67S93W/3SWW  
Location ID: 334649



**Photo 2.** Photo shows a drain line bull plug not installed.





Inspection Photos  
Location Name: GMR-67S93W/3SWSW  
Location ID: 334649



11/28/22  
65,-107.768790  
244° SW



**Photo 3.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702800991



**Inspection Photos**  
**Location Name: GMR-67S93W/3SWSW**  
**Location ID: 334649**



**Photo 4.** Photos show interim areas are well vegetated with perennial grasses.