

Inspection Photos

November 28, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 433706

Location Name: Rose/K22W

Inspection Document #: 702800993

Garfield County, CO

NESW Section 22 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rose/K22W
Location ID: 433706



Photo 1. Photo taken from the northwest shows an overview of the location.



Inspection Photos
Location Name: Rose/K22W
Location ID: 433706



Photo 2. Photos show examples of List B Noxious Weeds found throughout the interim areas (bull thistle, houndstongue).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800993

Inspection Photos
Location Name: Rose/K22W
Location ID: 433706



Photo 3. Photos show examples of List B Noxious Weeds found throughout the interim areas (musk thistle, plumeless thistle).

Inspection Photos
Location Name: Rose/K22W
Location ID: 433706



Photo 4. Photos shows production areas.

Inspection Photos
Location Name: Rose/K22W
Location ID: 433706



Photo 5. Photos show perennial grasses are well established in interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800993