

Inspection Photos

November 28, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334616

Location Name: PARKER RANCH-67S93W/22SWNE

Inspection Document #: 702800995

Garfield County, CO

SWNE Section 22 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: PARKER RANCH-67S93W/22SWNE

Location ID: 334616



Photo 1. Photo taken from the north shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800995

Inspection Photos
Location Name: PARKER RANCH-67S93W/22SWNE
Location ID: 334616



Photo 2. Photos show examples of List B Noxious Weeds found throughout the location (bull, plumeless, scotch thistles).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800995

Inspection Photos
Location Name: PARKER RANCH-67S93W/22SWNE
Location ID: 334616



Photo 3. Photos shows production areas.



Inspection Photos

Location Name: PARKER RANCH-67S93W/22SWNE

Location ID: 334616



Photo 4. Photos show perennial grasses are well established in interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800995