

Inspection Photos

November 28, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334565

Location Name: PITMAN-67S93W/13SEnw

Inspection Document #: 702800997

Garfield County, CO

NENW Section 13 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PITMAN-67S93W/13SENW
Location ID: 334565



Photo 1. Photo shows production areas.



Inspection Photos
Location Name: PITMAN-67S93W/13SENW
Location ID: 334565



Photo 2. Photos shows production areas.



Inspection Photos

Location Name: PITMAN-67S93W/13SENW

Location ID: 334565



Photo 3. Photos show perennial grasses are well established in interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800997