

# Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 12/1/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest along the access road. There are some check dams where stormwater is going around the check dam. BMP maintenance is needed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 12/1/2022

## Inspection Photos



**Photo 2.** Facing north toward the location. Interim reclamation has been performed and the location is reduced in size.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 12/1/2022

## Inspection Photos



**Photo 3.** Facing northeast toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 12/1/2022

## Inspection Photos



**Photo 4.** The topsoil pile has mostly been used for interim reclamation. This area appears to have been seeded and mulched but vegetation has not yet established. There are displaced wattles that need to be reinstalled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 12/1/2022

## Inspection Photos



**Photo 5.** Facing toward the tank battery which has been labeled.



## Inspection Photos



**Photo 6.** Facing toward the pumpjack. Erosion was repaired with rock ri/rap.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 12/1/2022

## Inspection Photos



**Photo 7.** Facing south at the east side of the location. There are some wattles in this area that are displaced and need maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 12/1/2022

## Inspection Photos



**Photo 8.** Facing northwest toward the location. The interim reclamation area appears to have been seeded and mulched but vegetation has not yet established. There are mostly undesirable weeds which will need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06219 | Date: 12/1/2022