

Inspection Photos

API: 043-06222

Operator: INCREMENTAL OIL & GAS LLC

Inspection Date: 12/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06222 | Date: 12/1/2022

Inspection Photos



Photo 1. Facing northwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 12/1/2022

Inspection Photos



Photo 2. Facing west toward the location. The degraded wattles previously observed were removed. The location consists of mostly undesirable weeds (Kochia, Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 12/1/2022

Inspection Photos



Photo 3. Facing northwest toward the location. The degraded wattles previously observed were removed. The location consists of mostly undesirable weeds (Kochia, Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 12/1/2022