

Inspection Photos

API: 043-06142

Operator: JAVERNICK OIL

Inspection Date: 12/1/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/1/2022

Inspection Photos



Photo 1. West side of the location facing east. The perennial vegetation is not establishing and additional seeding needs to be performed before the next growing season.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/1/2022

Inspection Photos



Photo 2. East side of the location facing west. The perennial vegetation is not establishing and additional seeding needs to be performed before the next growing season.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/1/2022

Inspection Photos



Photo 3. View of ground cover shows no desirable vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/1/2022

Inspection Photos



Photo 4. Drone aerial photo facing west taken during previous inspection. The approximate disturbance area of the location is circled which needs to be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/1/2022