

Inspection Photos

Location Name: Walcker USX AB/01-06P

Location #: 415959



Photo #1

Walcker USX AB 01-06P (123-31251) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 10 yds.



Photo #2

Walcker USX AB 01-07P, 01-05P, 01-08P Battery site

Active ; Equipment documented: Loc. # 415995

Formerly served:

Walcker USX AB 01-06P ;

Plugged & Abandoned | PA



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources