

Inspection Photos

November 23, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 414880

Location Name: 20F/Pad

Inspection Document #: 702800962

Garfield County, CO

SWNW Section 20 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: 20F/Pad
Location ID: 414880



Photo 1. Photo shows the reclaimed location to the southwest. Photo also shows plumeless thistle (List B Noxious)



Photo 2. Photo taken from the south shows an overview of the reclaimed location.

Inspection Photos
Location Name: 20F/Pad
Location ID: 414880



Photo 3. Photo taken from the western edge of the location shows a stormwater ditch which must be removed for the location to pass final reclamation. Line indicates where the ditch continues onto the location.



Photo 4. Photo taken from the west of the location shows the stormwater ditch pictured in Photo 2. Line indicates where the ditch continues off location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800962

Inspection Photos
Location Name: 20F/Pad
Location ID: 414880



Photo 5. Photo shows three (3) risers at the northwest of the location. Risers must be removed per 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800962