

Inspection Photos

November 23, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 382810

Location Name: CLOUGH-66S93W/7NENW

Inspection Document #: 702800974

Garfield County, CO

NENW Section 7 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CLOUGH-66S93W/7NENW

Location ID: 382810



Photo 1. Photo shows the access road culvert remains.



Photo 2. Photo shows the access road remains. Portions of the two-track to the south of the culvert lack vegetation in tracks and require additional reclamation. Note center of road is well vegetated.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800974

Inspection Photos
Location Name: CLOUGH-66S93W/7NENW
Location ID: 382810



Photo 3. Photos shows the access road to the north of the culvert is well vegetated.



Inspection Photos

Location Name: CLOUGH-66S93W/7NENW

Location ID: 382810



Photo 4. Photo shows seeding has largely failed and erosion is widespread in portions of the location to the south.



Photo 5. Photo taken from the south of the location shows where erosion pictured in Photo 7 converges to form a network of interconnected gullies. Arrow indicates a scaling device, which is 8 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800974

Inspection Photos

Location Name: CLOUGH-66S93W/7NENW

Location ID: 382810



Photo 6. Photo shows gully erosion at the southeast of the location where perennial establishment is poor. Scaling device is 8 inches tall.



Photo 7. Photo shows gully erosion at the south of the location where perennial establishment is poor.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800974

Inspection Photos

Location Name: CLOUGH-66S93W/7NENW

Location ID: 382810



11/23/22
+39.544490,-107.822343
76° E

Photo 8. Photo taken from the west shows an overview of the reclaimed location. Desirable perennial vegetation is well established.



11/23/22
+39.544808,-107.821844
222° SW

Photo 9. Photo taken from the east shows an overview of the reclaimed location. Desirable perennial vegetation is well established.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800974