

Inspection Photos
Location Name: HSR-Lost Creek State 1-32
Location ID: 3300765



Photo 1 – Pumping Unit – WEEDS

Photo 2 – Pumping Unit – WEEDS

Inspection Photos
Location Name: HSR-Lost Creek State 1-32
Location ID: 3300765



Photo 3 – Pumping Unit – WEEDS

Photo 4 – Wellhead Sign – Well Name no longer visible

Inspection Photos
Location Name: Hobe State 2-32
Location ID: 330074



Photo 5 – Unused Chemical