

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403247529

Date Received:

12/02/2022

Spill report taken by:

Brown, Kari

Spill/Release Point ID:

483380

### SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

#### OPERATOR INFORMATION

Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u>	Operator No: <u>10633</u>	<b>Phone Numbers</b>
Address: <u>1801 CALIFORNIA STREET #2500</u>		Phone: <u>(720) 315-8934</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>( )</u>
Contact Person: <u>Luke Kelly</u>		Email: <u>Lkelly@CiviResources.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

#### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403247529

Initial Report Date: 12/02/2022 Date of Discovery: 12/01/2022 Spill Type: Recent Spill

##### Spill/Release Point Location:

QTRQTR SWSW SEC 22 TWP 2N RNG 68W MERIDIAN 6

Latitude: 40.119628 Longitude: -104.994890

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

##### Reference Location:

Facility Type: TANK BATTERY  Facility/Location ID No 434171

Spill/Release Point Name: Jillson-East Rinn 22H-M268  Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=1 and <5

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

##### Land Use:

Current Land Use: CROP LAND Other(Specify): \_\_\_\_\_

Weather Condition: Clear

Surface Owner: FEE Other(Specify): \_\_\_\_\_

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A compromised gasket on the Jillson East Rinn 3B-22H-M268 separator resulted in approximately 3 bbls of produced water being released inside an unlined containment. The separator was immediately shut-in and the pooled fluid was removed. The impacted soil will be removed following the clearance of utility locates. Confirmation soil samples will be collected and submitted for laboratory analysis in compliance with COGCC Table 915-1. Analytical results will be provided in a subsequent report.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
12/2/2022	Surface Owner	on file	-on file	Notified of release
12/2/2022	Weld Co. OEM	Dave Burns	-on file	Notified via OEM report

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
Was there damage during excavation? \_\_\_\_\_  
Was CO 811 notified prior to excavation? \_\_\_\_\_

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- The presence of free product or hydrocarbon sheen Surface Water
- The presence of free product or hydrocarbon sheen on Groundwater
- The presence of contaminated soil in contact with Groundwater
- The presence of contaminated soil in contact with Surface water

No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.  <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>12/02/2022</u>		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	<u>0</u>	<u>0</u>	<input type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	<u>3</u>	<u>0</u>	<input type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>35</u>		Width of Impact (feet): <u>11</u>	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
The extent of the release was determined via initial environmental site assessment			
Soil/Geology Description:			
SM - silty sand			
Depth to Groundwater (feet BGS) <u>20</u>		Number Water Wells within 1/2 mile radius: <u>2</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>1850</u> None <input type="checkbox"/>	Surface Water <u>260</u> None <input type="checkbox"/>	
	Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
	Livestock <u>720</u> None <input type="checkbox"/>	Occupied Building <u>970</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			
NA			

### CORRECTIVE ACTIONS

#1 Supplemental Report Date: 12/02/2022

Root Cause of Spill/Release Equipment Failure

Other (specify)

Type of Equipment at Point of Spill/Release: Horizontal Heated Separator

If "Other" selected above, specify or describe here:

Empty text box for specifying other equipment details.

Describe Incident & Root Cause (include specific equipment and point of failure)

A compromised gasket on a flanged valve on the Jillson East Rinn 3B-22H-M268 separator resulted in approximately 3 bbls of produced water being released inside an unlined containment.

Describe measures taken to prevent the problem(s) from reoccurring:

Crestone field personnel are coached to inspect their equipment daily and to replace or repair worn or aged components

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation) [ ] Offsite Disposal [ ] Onsite Treatment [ ] Other (specify)

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

### REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

- Basis for Closure: [ ] Corrective Actions Completed (documentation attached, check all that apply)
[ ] Horizontal and Vertical extents of impacts have been delineated.
[ ] Documentation of compliance with Table 915-1 is attached.
[ ] All E&P Waste has been properly treated or disposed.
[ ] Work proceeding under an approved Form 27 (Rule 912.c).
Form 27 Remediation Project No:
[ ] SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

### OPERATOR COMMENTS:

Empty text box for operator comments.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Print Name: Luke Kelly

Title: Env Compliance Supervisor Date: 12/02/2022 Email: Lkelly@CiviResources.com

**COA Type****Description**

	Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director.
1 COA	

**Attachment List****Att Doc Num****Name**

403247529	SPILL/RELEASE REPORT(I/S)
403247741	TOPOGRAPHIC MAP
403250799	FORM 19 SUBMITTED

Total Attach: 3 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)