

Big Mountain Viper Figure 1A

Produced Water Release Extents

Site boundary fence

Surveyed extents of produced water impacts

SS1

SS2

SS5

SS3

SS4

SS8

SS9

SS11

SS6

SS7

BS1

BS2

Release location and primary excavation

Proposed shallow excavation extents

Exceedance of Table 915 for SAR and Conductivity at 6". Only exceeded conductivity at 1' depth.

Exceedance of Table 915 for SAR and Conductivity at 6" clean at 1'

Additional confirmation sample collected 11/10 and 11/11

N