

## Inspection Photos

Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: 483326

Inspection Date: December 6, 2022



Photo #1 – Well pad sign.

Photo #2 - Straw wattles stored at valve can/Point of Release (POR) area.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: 483326

Inspection Date: December 6, 2022



**Photo #3 – Excavated valve cans.**



**Photo #4 – View inside of excavation. Hydrocarbon odors were observed in this area during inspection.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: 483326

Inspection Date: December 6, 2022



**Photo #5 – Off-site impacted area (NW of pad) was covered with snow on inspection date.**



**Photo #6 – Overview of pad from NW corner.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Gunderson 20-03 Pad and Spill/Release

Location ID: #449070 & Spill/Release ID: 483326

Inspection Date: December 6, 2022



**Photo #7 – View into NW corner of tank battery secondary containment.**

**Photo #8 - View into east side of tank battery secondary containment.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources