

# Interim Reclamation and Stormwater Inspection

Date: 12/01/2022

Operator: FUNDARE RESOURCES OPERATING COMPANY- 10773

Location ID: 426841

Inspection Document #: 696105632

Weld County, CO

NENW Section 36 T10N R59W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Wolf #36-3624H  
Location ID: 426841



**Photo 1.** Taken from entrance, facing north. Photo illustrates presence of undesirable vegetation (e.g. kochia and russian thistle).




Inspection Photos  
Location Name: Wolf #36-3624H  
Location ID: 426841



**Photo 2.** Taken from southeastern portion of location, facing north. See comments in Photo 1.



Inspection Photos  
Location Name: Wolf #36-3624H  
Location ID: 426841



**Photo 3.** Taken from the western portion of the location, facing northwest. See comments in Photo 1.

Inspection Photos  
Location Name: Wolf #36-3624H  
Location ID: 426841



**Photo 4.** Taken near the northwest corner, facing northwest. See comments in Photo 1.



Inspection Photos  
Location Name: Wolf #36-3624H  
Location ID: 426841



**Photo 5.** Taken south of the treater/building, facing northwest. Photo illustrates no emergency contact information and illegible signage.



Inspection Photos  
Location Name: Wolf #36-3624H  
Location ID: 426841



**Photo 6.** Taken from northern portion of location, facing northeast. Photo shows unused pipe and fittings that need to be removed if not currently in use.



**Photo 7.** Pump jack photo illustrating a bird nest in equipment.