

# Final Reclamation and Stormwater Inspection

Date: 12/01/2022

Operator: WHITING OIL & GAS CORP - 96155

Location ID: 441391

Inspection Document #: 696105640

Weld County, CO

NWSW Section 29 T10N R58W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Razor 29 L Pad  
Location ID: 441391



**Photo 1.** Taken from southern portion of location, facing north. Photo illustrates the location is predominantly undesirable vegetation (e.g. russian thistle). Location appears to have been reclaimed as the topsoil stockpiles have been placed to their original contour/position and no evidence of ditch and berm were observed.

Inspection Photos  
Location Name: Razor 29 L Pad  
Location ID: 441391



**Photo 2.** Taken from the southwest corner of location, facing north. Photo illustrates the reference area (predominantly buffalo grass) on the outside of the fence, and perimeter fence that remains on location. The fence is now considered debris and needs to be removed.