

# Final Reclamation and Stormwater Inspection

Date: 11/22/2022

Operator: MAGPIE OPERATING LLC - 52530

Location ID: 312143

Inspection Document #: 696105620

Logan County, CO

SESE Section 30 T8N R53W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Warnecke #1  
Location ID: 312143



**Photo 1.** Taken near the entrance to the location, facing northwest. Photo illustrates the operator has removed the fence and gate required by previous corrective actions (Doc #696105548). It also appears that the operator has removed some material (likely road base) from the entrance approach.



Inspection Photos  
Location Name: Warnecke #1  
Location ID: 312143



**Photo 2.** Taken near the entrance to the location, facing south. See comments in Photo 1.

Inspection Photos  
Location Name: Warnecke #1  
Location ID: 312143



**Photo 3.** Taken from the entrance of the location, facing west. Photo illustrates that the undesirable vegetation has been managed (e.g. mowed) and the manure piles left undisturbed as requested by the surface owner. Photo also shows that it appears no other reclamation work has been performed at the time of this inspection.



Inspection Photos  
Location Name: Warnecke #1  
Location ID: 312143



11/22/22, 4:23 PM  
135° SE

**Photo 4.** Taken from the pit location, facing southeast. Photo illustrates that the undesirable vegetation has been mowed and that no other reclamation appears to have been performed at the time of this inspection.



Inspection Photos  
Location Name: Warnecke #1  
Location ID: 312143



**Photo 5.** Taken from the western portion of the location, facing west. Photo illustrates that the access road leading to the well location has not been reclaimed.