

Inspection Photos

12/7/2022

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334697

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334697



December 7, 2022



December 7, 2022

Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the location from east, southeast, southwest to west.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334697



December 7, 2022



December 7, 2022

Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334697



Photo 3: Photo shows open valve at the condensate tank has been covered with wire netting.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334697



Photo 4: Tank battery facility.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334697



December 7, 2022



December 7, 2022

Photo 5: Photos examples showing the interim areas. Photo right shows possible stockpile of rock.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources