

# Inspection Photos

API: 071-06819

Operator: WAPITI OPERATING LLC

Inspection Date: 12/7/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06819 | Date: 12/7/2022

## Inspection Photos



**Photo 1.** The tree debris has been cleaned up and removed where grading had pushed over the trees.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06819 | Date: 12/7/2022

## Inspection Photos



**Photo 2.** Facing northwest toward the wellsite. It appears electric lines were removed. This area of disturbance needs to be seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06819 | Date: 12/7/2022



## Inspection Photos



**Photo 3.** Facing northwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06819 | Date: 12/7/2022