

# Inspection Photos

December 7, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334561

Location Name: SCHAEFFER-67S93W/11NESE

Inspection Document #: 702801013

Garfield County, CO

NESE Section 11 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SCHAEFFER-67S93W/11NESE  
Location ID: 334561



**Photo 1.** Photos show production areas. Note sign installed at tank battery.

Inspection Photos  
Location Name: SCHAEFFER-67S93W/11NESE  
Location ID: 334561

12/7/22  
+39.458886,-107.737086  
48° NE



12/7/22  
+39.458886,-107.737086  
85° E



**Photo 2.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801013

Inspection Photos

Location Name: SCHAEFFER-67S93W/11NESE

Location ID: 334561



**Photo 3.** Photo shows interim areas at the northeast of the location are vegetated with perennial grasses and shrubs.



**Photo 4.** Photo shows interim areas at the northwest of the location are vegetated with perennial grasses and shrubs.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801013

Inspection Photos

Location Name: SCHAEFFER-67S93W/11NESE

Location ID: 334561



Photo 5. Photo shows access road erosion from the 12/7/22 inspection (left) and previous 8/20/21 inspection (right).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801013